

Tell Mozan Monitoring Checklist

Name: ...Amer Ahmad.....

Date: 2025. 08. 06

All checklist items must be documented with date-stamped photographs.

Archaeological Areas

Temple Area

	Task	Purpose	Photo Required
<input checked="" type="checkbox"/>	Overview, General inspection	<u>General Check</u>	Yes
<input checked="" type="checkbox"/>	Check temple area for erosion, debris, vegetation	<u>Site Maintenance and Visitors</u> — Visitor safety & preservation	Yes
<input checked="" type="checkbox"/>	Inspect plaster on temple structure	<u>Site Preservation</u> — Identify surface deterioration	Yes
<input checked="" type="checkbox"/>	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — growth damage, fire prevention	Yes
<input checked="" type="checkbox"/>	Inspect paths: cleanliness and visibility	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes
<input checked="" type="checkbox"/>	Inspect Temple panorama (paint, assess structural condition, clean glass, paper condition, laminate and replace worn or missing pages, repaint the exterior to blend with the environment, the casing)	<u>Site Maintenance and Visitors</u> — Public communication quality and Interpretive quality, visitor, visibility, durability, aesthetic presentation, visual integration	Yes
<input checked="" type="checkbox"/>	Inspect panorama and panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes



Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes
Additional Points and Notes: Observations: <ul style="list-style-type: none"> - There were a few weeds in the area of the Lion Temple, and significantly more in the area of the German excavation??, in front of the Great Staircase - The removed weeds were gathered in front J3 - A few pages of the signs are missing in the temple area - There is no erosion on the walls of the temple - Some debris has been observed accumulating in one corner of the Lion Temple - The corner of the Panorama is broken - The sign structures are in good condition - No burning activity observed Suggestions: <ul style="list-style-type: none"> - The inspection of the Panorama is mentioned twice in the file, while the signs in the temple area are not mentioned at all. Please correct it. - The pathways in the temple area require more attention and should be cleaned - Remove the phrase “erosion” and place it together with “inspecting plaster on temple structure” in the file - Remove the phrase " vegetation" and “debris” and place it together with " Checking for weed removal" in the file. - Reordering the pages of the signs based on the observations from the website 		

Monumental Staircase



Task	Purpose	Photo Required
Overview, General inspection	<u>General Check</u>	Yes
Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes
Inspect stones, plaster joints	<u>Site Preservation and Maintenance</u> — Structural preservation	Yes
Inspect clear vegetation and debris	<u>Site Preservation, Maintenance, and Visit</u> — Safety and conservation	Yes
Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes

☒	Inspect clean paths	<u>Site Maintenance and Visitors</u> —Visitor safety & appearance	Yes
☒	Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes
Additional Points and Notes: Observations: <ul style="list-style-type: none"> - No burning activity observed - The stones are well joined, and the mortar is in good condition - The pathways require more attention and should be cleaned - There were a few weeds in the area of the Lion Temple, and significantly more in the area of the German excavation??, in front of the Great Staircase - The signs are in good condition - No nylon was found on the eastern wall of the staircase (Betili pillars) 			

Excavation Areas (J1, J5)

	Task	Purpose	Photo Required
☒	Overview, General inspection	<u>General Check</u>	Yes
☒	Check for wall cracks/collapses (J1)	<u>Site Preservation</u> — Structural risk	Yes
☒	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes
☒	Inspect clean paths	<u>Site Maintenance and Visitors</u> —Visitor safety & appearance	Yes
☒	Inspect protective burlap J1	<u>Site Maintenance</u> — Ensure structural protection	Yes
☒	Assess protective system (tarps, sandbags)	<u>Site Preservation</u> — Weather protection	Yes
☒	Replace deteriorated sandbags (esp. under J1 section)	<u>Site Preservation</u> — Prevent collapse	Yes
☒	Check and Clean staircase at J5	<u>Site Preservation, Maintenance, and Visit</u> — Visitor access & safety	Yes
☒	Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes
☒	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes

Additional Points and Notes:**Observations:**

- Some cracks and signs of collapse were observed in the J1 section
- A few weeds were observed in the J1 and J5 area
- The pathways in the J1 and J5 areas require more attention and should be cleaned in both J1 and J5 areas
- Dirt was observed on the floor of J1
- The burlap is deteriorated and needs to be replaced
- The sandbags are deteriorated and need to be replaced
- The signs are in good condition in both J1 and J5
- No burning activity observed
- The sandbags of the retaining wall in the J5 area are deteriorated

Abi Complex

	Task	Purpose	Photo Required
<input checked="" type="checkbox"/>	Overview, General inspection	<u>General Check</u>	Yes
<input checked="" type="checkbox"/>	Check dome and shaft structure	<u>Site Maintenance</u> — Structural integrity	Yes
<input checked="" type="checkbox"/>	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes
<input checked="" type="checkbox"/>	Inspect clean path	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes
<input checked="" type="checkbox"/>	Assess cleanliness of <i>abi</i> interior	<u>Site Visit</u> — Visitor safety	Yes
<input checked="" type="checkbox"/>	Inspect the entrance metal sheets (rust, dents)	<u>Site Maintenance</u> — Protective function	Yes
<input checked="" type="checkbox"/>	Check the paint touch-up for the entrance	<u>Site Maintenance</u> — Prevent corrosion	Yes
<input checked="" type="checkbox"/>	Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes
<input checked="" type="checkbox"/>	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes

Additional Points and Notes:**Observations:**

- The dome is slightly scratched and needs to be repainted
- No weeds
- The interior pathway require more attention and should be cleaned
- Dirt was observed inside Abi
- The entrance metal sheets need to be repainted
- The sign is in good condition
- No burning activity observed

Palace Area

	Task	Purpose	Photo Required
<input checked="" type="checkbox"/>	Overview, General inspection	<u>General Check</u>	Yes
<input checked="" type="checkbox"/>	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes
<input checked="" type="checkbox"/>	Inspect clean paths	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes
<input checked="" type="checkbox"/>	Inspect protective burlap (esp. Wall C2-3 and H3–H1)	<u>Site Maintenance</u> — Ensure structural protection	Yes
<input checked="" type="checkbox"/>	Check for cracks or collapse (esp. Wall C2-3)	<u>Site Maintenance</u> — Prevent structural failure	Yes
<input checked="" type="checkbox"/>	Inspect plastic and nylon sheeting	<u>Site Maintenance</u> — Assess water infiltration protection	Yes
<input checked="" type="checkbox"/>	Check sewage cover in Room C5	<u>Site Maintenance</u> — Safety hazard prevention	Yes
<input checked="" type="checkbox"/>	Inspect Tannur cover in Royal Wing	<u>Site Maintenance</u> — Structural preservation	Yes
<input checked="" type="checkbox"/>	Inspect the royal courtyard (area A16).	<u>Site Maintenance</u> — Prevent structural failure	Yes
<input checked="" type="checkbox"/>	Inspect Palace panorama (paint, assess structural condition, clean glass, paper condition, laminate and replace worn or missing pages, repaint the exterior to blend with the environment, the casing)	<u>Site Maintenance and Visitors</u> — Public communication quality and Interpretive quality, visitor, visibility, durability, aesthetic presentation, visual integration	Yes
<input checked="" type="checkbox"/>	Evaluate visual harmony of panorama casing	<u>Site Visit</u> — Aesthetic integration	Yes
<input checked="" type="checkbox"/>	Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes
<input checked="" type="checkbox"/>	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes

Additional Points and Notes:**Observations:**

- Weeds were observed in front of the palace (the southwest side)
- The pathways in Palace areas require more attention and should be cleaned in
- The burlap in wall C2-3 is in good condition
- Wall C2-3 has many cracks and is in very poor condition, and the nylon was not fixed properly
- The wall H3-H1 has no cover
- There is no nylon on either wall C1-1 or H3-H1
- The sewage cover is not properly fixed
- The signs are in good condition
- The cover of the Tannur is broken
- There are some weeds on the floor of the courtyard in the area A16, and the northern section is crumbled
- Panorama in good condition
- Panorama casing is in good condition
- The signs are in good condition
- The protective system needs to be re-plastered
- No burning activity observed
- There are some gaps on the burlap
- The burlap on the wall B2-1 and the external face of the wall C2-3 need to be changed

Excavation Areas Above Palace

	Task	Purpose	Photo Required
<input type="checkbox"/>	Overview, General inspection	<u>General Check</u>	Yes
<input type="checkbox"/>	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes
<input type="checkbox"/>	Inspect clean paths	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes
<input type="checkbox"/>	Inspect conservation measures	<u>Site Maintenance</u> — Ensure structural protection	Yes
<input type="checkbox"/>	Check for cracks or wall damage	<u>Site Maintenance</u> — Prevent structural failure	Yes
<input type="checkbox"/>	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes
Additional Points and Notes:			

Reporting Procedure

Each point must be accompanied by:

A minimum of one clear, time-stamped photo

Notes on condition, action taken, or further action needed

Submit the checklist and photo archive to the site director and conservation lead by email









































