

Tell Mozan Monitoring Checklist

Name: ...Amer Ahmad.....

Date: 2025. 09. 30

All checklist items must be documented with date-stamped photographs.

Archaeological Areas

Temple Area

	Task	Purpose	Photo Required
<input type="checkbox"/>	Overview, General inspection	<u>General Check</u>	Yes
<input type="checkbox"/>	Check temple area for erosion, debris, vegetation	<u>Site Maintenance and Visitors</u> — Visitor safety & preservation	Yes
<input type="checkbox"/>	Inspect plaster on temple structure	<u>Site Preservation</u> — Identify surface deterioration	Yes
<input type="checkbox"/>	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — growth damage, fire prevention	Yes
<input type="checkbox"/>	Inspect paths: cleanliness and visibility	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes
<input type="checkbox"/>	Inspect Temple panorama (paint, assess structural condition, clean glass, paper condition, laminate and replace worn or missing pages, repaint the exterior to blend with the environment, the casing)	<u>Site Maintenance and Visitors</u> — Public communication quality and Interpretive quality, visitor, visibility, durability, aesthetic presentation, visual integration	Yes
<input type="checkbox"/>	Inspect panorama and panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes

☒	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes
Additional Points and Notes: - The overall condition of the temple area is good			

Monumental Staircase

	Task	Purpose	Photo Required
☒	Overview, General inspection	<u>General Check</u>	Yes
☒	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes
☒	Inspect stones, plaster joints	<u>Site Preservation and Maintenance</u> — Structural preservation	Yes
☒	Inspect clear vegetation and debris	<u>Site Preservation, Maintenance, and Visit</u> — Safety and conservation	Yes
☒	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes
☒	Inspect clean paths	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes
☒	Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes
Additional Points and Notes: - No nylon was found on the eastern wall of the staircase (Betili pillars) - There is slight erosion in the section opposite the staircase - The overall condition is good			

Excavation Areas (J1, J5)

	Task	Purpose	Photo Required
☒	Overview, General inspection	<u>General Check</u>	Yes
☒	Check for wall cracks/collapses (J1)	<u>Site Preservation</u> — Structural risk	Yes
☒	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes
☒	Inspect clean paths	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes
☒	Inspect protective burlap J1	<u>Site Maintenance</u> — Ensure structural protection	Yes
☒	Assess protective system (tarps, sandbags)	<u>Site Preservation</u> — Weather protection	Yes
☒	Replace deteriorated sandbags (esp. under J1 section)	<u>Site Preservation</u> — Prevent collapse	Yes
☒	Check and Clean staircase at J5	<u>Site Preservation, Maintenance, and Visit</u> — Visitor access & safety	Yes
☒	Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes
☒	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes
Additional Points and Notes: <ul style="list-style-type: none"> - The overall condition of both areas J1 and J5 is good. We will replace the sandbags in J5 later. - The burlap in area J1 has been replaced 			

Abi Complex

	Task	Purpose	Photo Required
<input checked="" type="checkbox"/>	Overview, General inspection	<u>General Check</u>	Yes
<input checked="" type="checkbox"/>	Check dome and shaft structure	<u>Site Maintenance</u> — Structural integrity	Yes
<input checked="" type="checkbox"/>	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes
<input checked="" type="checkbox"/>	Inspect clean path	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes
<input checked="" type="checkbox"/>	Assess cleanliness of <i>abi</i> interior	<u>Site Visit</u> — Visitor safety	Yes
<input checked="" type="checkbox"/>	Inspect the entrance metal sheets (rust, dents)	<u>Site Maintenance</u> — Protective function	Yes
<input checked="" type="checkbox"/>	Check the paint touch-up for the entrance	<u>Site Maintenance</u> — Prevent corrosion	Yes
<input checked="" type="checkbox"/>	Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes
<input checked="" type="checkbox"/>	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes
Additional Points and Notes: <ul style="list-style-type: none"> - The overall condition is good - The dome and the entrance have been painted 			

Palace Area

	Task	Purpose	Photo Required
<input checked="" type="checkbox"/>	Overview, General inspection	<u>General Check</u>	Yes
<input checked="" type="checkbox"/>	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes
<input checked="" type="checkbox"/>	Inspect clean paths	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes

☒	Inspect protective burlap (esp. Wall C2-3 and H3–H1)	<u>Site Maintenance</u> — Ensure structural protection	Yes
☒	Check for cracks or collapse (esp. Wall C2-3)	<u>Site Maintenance</u> — Prevent structural failure	Yes
☒	Inspect plastic and nylon sheeting	<u>Site Maintenance</u> — Assess water infiltration protection	Yes
☒	Check sewage cover in Room C5	<u>Site Maintenance</u> — Safety hazard prevention	Yes
☒	Inspect Tannur cover in Royal Wing	<u>Site Maintenance</u> — Structural preservation	Yes
☒	Inspect the royal courtyard (area A16).	<u>Site Maintenance</u> — Prevent structural failure	Yes
☒	Inspect Palace panorama (paint, assess structural condition, clean glass, paper condition, laminate and replace worn or missing pages, repaint the exterior to blend with the environment, the casing)	<u>Site Maintenance and Visitors</u> — Public communication quality and Interpretive quality, visitor, visibility, durability, aesthetic presentation, visual integration	Yes
☒	Evaluate visual harmony of panorama casing	<u>Site Visit</u> — Aesthetic integration	Yes
☒	Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed)	<u>Site Maintenance and Visitors</u> — Visitor guidance and interpretive quality, durability, aesthetic presentation	Yes
☒	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes
Additional Points and Notes: <ul style="list-style-type: none"> - The overall condition is good, except for Wall C2-3, which is very crumbly. I am going to assess all the palace walls soon. 			

Excavation Areas Above Palace

	Task	Purpose	Photo Required
<input type="checkbox"/>	Overview, General inspection	<u>General Check</u>	Yes
<input type="checkbox"/>	Check for weed removal	<u>Site Maintenance and Risks Prevention</u> — Fire prevention	Yes
<input type="checkbox"/>	Inspect clean paths	<u>Site Maintenance and Visitors</u> — Visitor safety & appearance	Yes
<input type="checkbox"/>	Inspect conservation measures	<u>Site Maintenance</u> — Ensure structural protection	Yes
<input type="checkbox"/>	Check for cracks or wall damage	<u>Site Maintenance</u> — Prevent structural failure	Yes
<input type="checkbox"/>	Verify no unauthorized burning activity	<u>Risks Prevention</u> — Site safety	Yes
Additional Points and Notes: - The overall condition is good			

Reporting Procedure

Each point must be accompanied by:

A minimum of one clear, time-stamped photo

Notes on condition, action taken, or further action needed

Submit the checklist and photo archive to the site director and conservation lead by email





30/09/2025 10:06



30/09/2025 10:05





































