**Tell Mozan Monitoring Checklist**

**Name:** …Amer Ahmad……

**Date:** 2025. 08. 06

All checklist items must be documented with date-stamped photographs.

**Archaeological Areas**

**Temple Area**

| | Task | Purpose | Photo Required |
|---|---|---|---|
| ☒ | Overview, General inspection | General Check | Yes |
| ☒ | Check temple area for erosion, debris, vegetation | Site Maintenance and Visitors — Visitor safety & preservation | Yes |
| ☒ | Inspect plaster on temple structure | Site Preservation — Identify surface deterioration | Yes |
| ☒ | Check for weed removal | Site Maintenance and Risks Prevention — growth damage, fire prevention | Yes |
| ☒ | Inspect paths: cleanliness and visibility | Site Maintenance and Visitors — Visitor safety & appearance | Yes |
| ☒ | Inspect Temple panorama (paint, assess structural condition, clean glass, paper condition, laminate and replace worn or missing pages, repaint the exterior to blend with the environment, the casing) | Site Maintenance and Visitors — Public communication quality and Interpretive quality, visitor, visibility, durability, aesthetic presentation, visual integration | Yes |
| ☒ | Inspect panorama and panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed) | Site Maintenance and Visitors — Visitor guidance and interpretive quality, durability, aesthetic presentation | Yes |

| | | | |
|---|---|---|---|
| ☒ | Verify no unauthorized burning activity | Risks Prevention — Site safety | Yes |

**Additional Points and Notes:**
**Observations:**

- **There were a few weeds in the area of the Lion Temple, and significantly more in the area of the German excavation??, in front of the Great Staircase**
- **The removed weeds were gathered in front J3**
- **A few pages of the signs are missing in the temple area**
- **There is no erosion on the walls of the temple**
- **Some debris has been observed accumulating in one corner of the Lion Temple**
- **The corner of the Panorama is broken**
- **The sign structures are in good condition**
- **No burning activity observed**

**Suggestions:**

- **The inspection of the Panorama is mentioned twice in the file, while the signs in the temple area are not mentioned at all. Please correct it.**
- **The pathways in the temple area require more attention and should be cleaned**
- **Remove the phrase “erosion” and place it together with “inspecting plaster on temple structure” in the file**
- **Remove the phrase " vegetation" and “debris” and place it together with " Checking for weed removal" in the file.**
- **Reordering the pages of the signs based on the observations from the website**

## Monumental Staircase

| | Task | Purpose | Photo Required |
|---|---|---|---|
| ☒ | Overview, General inspection | General Check | Yes |
| ☒ | Verify no unauthorized burning activity | Risks Prevention — Site safety | Yes |
| ☒ | Inspect stones, plaster joints | Site Preservation and Maintenance — Structural preservation | Yes |
| ☒ | Inspect clear vegetation and debris | Site Preservation, Maintenance, and Visit — Safety and conservation | Yes |
| ☒ | Check for weed removal | Site Maintenance and Risks Prevention — Fire prevention | Yes |

| | | | |
|---|---|---|---|
| ☒ | Inspect clean paths | Site Maintenance and Visitors —Visitor safety & appearance | Yes |
| ☒ | Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed) | Site Maintenance and Visitors — Visitor guidance and interpretive quality, durability, aesthetic presentation | Yes |
| | **Additional Points and Notes:**<br>**Observations:**<br>- **No burning activity observed**<br>- **The stones are well joined, and the mortar is in good condition**<br>- **The pathways require more attention and should be cleaned**<br>- **There were a few weeds in the area of the Lion Temple, and significantly more in the area of the German excavation??, in front of the Great Staircase**<br>- **The signs are in good condition**<br>- **No nylon was found on the eastern wall of the staircase (Betili pillars)** | | |

## Excavation Areas (J1, J5)

| | Task | Purpose | Photo Required |
|---|---|---|---|
| ☒ | Overview, General inspection | General Check | Yes |
| ☒ | Check for wall cracks/collapses (J1) | Site Preservation — Structural risk | Yes |
| ☒ | Check for weed removal | Site Maintenance and Risks Prevention — Fire prevention | Yes |
| ☒ | Inspect clean paths | Site Maintenance and Visitors —Visitor safety & appearance | Yes |
| ☒ | Inspect protective burlap J1 | Site Maintenance — Ensure structural protection | Yes |
| ☒ | Assess protective system (tarps, sandbags) | Site Preservation — Weather protection | Yes |
| ☒ | Replace deteriorated sandbags (esp. under J1 section) | Site Preservation — Prevent collapse | Yes |
| ☒ | Check and Clean staircase at J5 | Site Preservation, Maintenance, and Visit — Visitor access & safety | Yes |
| ☒ | Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed) | Site Maintenance and Visitors — Visitor guidance and interpretive quality, durability, aesthetic presentation | Yes |
| ☒ | Verify no unauthorized burning activity | Risks Prevention — Site safety | Yes |

**Additional Points and Notes:**
**Observations:**

- **Some cracks and signs of collapse were observed in the J1 section**
- **A few weeds were observed in the J1 and J5 area**
- **The pathways in the J1 and J5 areas require more attention and should be cleaned in both J1 and J5 areas**
- **Dirt was observed on the floor of J1**
- **The burlap is deteriorated and needs to be replaced**
- **The sandbags are deteriorated and need to be replaced**
- **The signs are in good condition in both J1 and J5**
- **No burning activity observed**
- **The sandbags of the retaining wall in the J5 area are deteriorated**

## Abi Complex

| | Task | Purpose | Photo Required |
|---|---|---|---|
| ☒ | Overview, General inspection | General Check | Yes |
| ☒ | Check dome and shaft structure | Site Maintenance — Structural integrity | Yes |
| ☒ | Check for weed removal | Site Maintenance and Risks Prevention — Fire prevention | Yes |
| ☒ | Inspect clean path | Site Maintenance and Visitors —Visitor safety & appearance | Yes |
| ☒ | Assess cleanliness of *abi* interior | Site Visit — Visitor safety | Yes |
| ☒ | Inspect the entrance metal sheets (rust, dents) | Site Maintenance — Protective function | Yes |
| ☒ | Check the paint touch-up for the entrance | Site Maintenance — Prevent corrosion | Yes |
| ☒ | Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed) | Site Maintenance and Visitors — Visitor guidance and interpretive quality, durability, aesthetic presentation | Yes |
| ☒ | Verify no unauthorized burning activity | Risks Prevention — Site safety | Yes |

**Additional Points and Notes:**
**Observations:**

- **The dome is slightly scratched and needs to be repainted**
- **No weeds**
- **The interior pathway require more attention and should be cleaned**
- **Dirt was observed inside Abi**
- **The entrance metal sheets need to be repainted**
- **The sign is in good condition**
- **No burning activity observed**

## Palace Area

| | Task | Purpose | Photo Required |
|---|---|---|---|
| ☒ | Overview, General inspection | General Check | Yes |
| ☒ | Check for weed removal | Site Maintenance and Risks Prevention — Fire prevention | Yes |
| ☒ | Inspect clean paths | Site Maintenance and Visitors — Visitor safety & appearance | Yes |
| ☒ | Inspect protective burlap (esp. Wall C2-3 and H3–H1) | Site Maintenance — Ensure structural protection | Yes |
| ☒ | Check for cracks or collapse (esp. Wall C2-3) | Site Maintenance — Prevent structural failure | Yes |
| ☒ | Inspect plastic and nylon sheeting | Site Maintenance — Assess water infiltration protection | Yes |
| ☒ | Check sewage cover in Room C5 | Site Maintenance — Safety hazard prevention | Yes |
| ☒ | Inspect Tannur cover in Royal Wing | Site Maintenance — Structural preservation | Yes |
| ☒ | Inspect the royal courtyard (area A16). | Site Maintenance — Prevent structural failure | Yes |
| ☒ | Inspect Palace panorama (paint, assess structural condition, clean glass, paper condition, laminate and replace worn or missing pages, repaint the exterior to blend with the environment, the casing) | Site Maintenance and Visitors — Public communication quality and Interpretive quality, visitor, visibility, durability, aesthetic presentation, visual integration | Yes |
| ☒ | Evaluate visual harmony of panorama casing | Site Visit — Aesthetic integration | Yes |
| ☒ | Inspect panels (paint, structure, clean dirt and glue residue, laminate and replace worn or missing pages, scrape and repaint metal structures if needed) | Site Maintenance and Visitors — Visitor guidance and interpretive quality, durability, aesthetic presentation | Yes |
| ☒ | Verify no unauthorized burning activity | Risks Prevention — Site safety | Yes |

**Additional Points and Notes:**

**Observations:**

- **Weeds were observed in front of the palace (the southwest side)**
- **The pathways in Palace areas require more attention and should be cleaned in**
- **The burlap in wall C2-3 is in good condition**
- **Wall C2-3 has many cracks and is in very poor condition, and the nylon was not fixed properly**
- **The wall H3-H1 has no cover**
- **There is no nylon on either wall C1-1 or H3-H1**
- **The sewage cover is not properly fixed**
- **The signs are in good condition**
- **The cover of the Tannur is broken**
- **There are some weeds on the floor of the courtyard in the area A16, and the northern section is crumbled**
- **Panorama in good condition**
- **Panorama casing is in good condition**
- **The signs are in good condition**
- **The protective system needs to be re-plastered**
- **No burning activity observed**
- **There are some gabs on the burlap**
- **The burlap on the wall B2-1 and the external face of the wall C2-3 need to be changed**

## Excavation Areas Above Palace

| | Task | Purpose | Photo Required |
|---|---|---|---|
| ☒ | Overview, General inspection | General Check | Yes |
| ☒ | Check for weed removal | Site Maintenance and Risks Prevention — Fire prevention | Yes |
| ☒ | Inspect clean paths | Site Maintenance and Visitors — Visitor safety & appearance | Yes |
| ☒ | Inspect conservation measures | Site Maintenance — Ensure structural protection | Yes |
| ☒ | Check for cracks or wall damage | Site Maintenance — Prevent structural failure | Yes |
| ☒ | Verify no unauthorized burning activity | Risks Prevention — Site safety | Yes |
| **Additional Points and Notes:** | | | |

## Reporting Procedure

Each point must be accompanied by:

**A minimum of one clear, time-stamped photo**

**Notes on condition, action taken, or further action needed**

**Submit the checklist and photo archive to the site director and conservation lead by email**

06/08/2025 10:35

06/08/2025 10:37

06/08/2025 10:37

06/08/2025 10:37

06/08/2025 10:39

06/08/2025 10:47

5
The Temple
of the Lion
معبد الأسد
06/08/2025 10:40

06/08/2025 10:40

06/08/2025 10:42

06/08/2025 10:41

06/08/2025 10:43

4
06/08/2025 10:43

06/08/2025 11:34

06/08/2025 10:52

06/08/2025 10:52

06/08/2025 10:52

06/08/2025 10:51

06/08/2025 10:51

06/08/2025 10:51

06/08/2025 10:54

06/08/2025 10:55

06/08/2025 10:54

06/08/2025 10:53

06/08/2025 11:03

06/08/2025 11:04

06/08/2025 11:10

06/08/2025 11:06

06/08/2025 11:07

06/08/2025 11:04

06/08/2025 11:10

06/08/2025 11:03

06/08/2025 11:25

06/08/2025 11:23

06/08/2025 11:11

06/08/2025 11:08

06/08/2025 11:09

06/08/2025 11:01

06/08/2025 11:09

06/08/2025 10:58

06/08/2025 10:57